

# Memorandum

**To** Manager Customer Connections, Manager Asset Solutions, Group Manager Resources, Network Compliance Auditors, Option 2 Contractors.

**Copy** Engineering Standards Manager

**Date** 31 July 2007


**Subject** **Network Compliance Bulletin #17** (Pits in Footpaths)

**Managers please circulate this bulletin to your teams.**  
This memorandum has been prepared to remind those involved in the design/construction of underground assets with a focus on the installation of service pits in footpaths.  
The requirements are detailed in the **CP / PAL Technical Standards** (GS021,- LV UG Mains & Service-Pits & Pillars, GS201- Pit Assembly - Service )

Attached is a photo of a non complying situation in a project that was recently constructed, there have also been other recent similar situations.



**Non Compliant Installation of a Service Pit (within the footpath expansion joint)**



**Compliant Installation of a Service Pit (minimum 150mm from any edge of the footpath including expansion joints)**  
Extract from Technical Standard GS021

Should you have further queries contact Les Ferris ph. 53272404 or Graeme Davenport ph. 53272238

Les Ferris  
Network Compliance Manager – Powercor